

CASE STUDY: The History of Water Supply on the Central Coast

APPENDIX 5: Schematic diagram of the rock strata (i.e. stratigraphy) for the selected Mangrove Creek dam site (see page 11).




Figure 11: Profile of rock strata at the Mangrove Creek Dam site. ("Mangrove Creek Dam Investigations", Volume 4, Report 1 of "Report on Investigations for Water Supply to the Gosford-Wyong Region", January 1975, Department of Public Works N.S.W., Figure 4 (modified))